

Report No.: FR8O2308B

# Appendix E. Setup Photographs

# <Conducted Emission>

#### Mode 1





Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7G Page Number : E1 of E3
Report Issued Date : Jan. 16, 2019
Report Version : Rev. 01


Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0




## <Radiated Emission>

### X Plane for Bluetooth LE v4.2

LF



HF



Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7G Page Number : E2 of E3
Report Issued Date : Jan. 16, 2019
Report Version : Rev. 01


Report No.: FR8O2308B

Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0




### Z Plane for Bluetooth LE v5.0

LF



HF



\_\_\_\_\_THE END\_\_\_\_

Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7G Page Number : E3 of E3
Report Issued Date : Jan. 16, 2019
Report Version : Rev. 01

Report No.: FR8O2308B

Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0