

Appendix A. Setup Photographs

<Conducted Emission>

Mode 4





Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RMSG6 Page Number : A1 of A4
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No. : FC762302



Mode 7





Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RMSG6 Page Number : A2 of A4
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No.: FC762302


<Radiated Emission>

Mode 4

LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RMSG6 Page Number : A3 of A4
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No.: FC762302

C Test Report No. : FC762302

Mode 6

LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RMSG6 Page Number : A4 of A4
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3