



Report No.: FR862604B

# Appendix E. Setup Photographs

## <Conducted Emission>

#### Mode 1





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE7TG Page Number : E1 of E3
Report Issued Date : Aug. 02, 2018
Report Version : Rev. 01


Report Template No.: BU5-FR15CBT4.0/5.0 Version 2.0



## <Radiated Emission>

#### Z Plane for Bluetooth LE v4.0

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE7TG Page Number : E2 of E3
Report Issued Date : Aug. 02, 2018
Report Version : Rev. 01

Report No.: FR862604B

Report Template No.: BU5-FR15CBT4.0/5.0 Version 2.0



### Z Plane for Bluetooth LE v5.0

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE7TG Page Number : E3 of E3
Report Issued Date : Aug. 02, 2018
Report Version : Rev. 01

Report No.: FR862604B

Report Template No.: BU5-FR15CBT4.0/5.0 Version 2.0