

Appendix D. Setup Photographs

<Conducted Emission> Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGZ3S00211 Page Number : D1 of D3

Report Issued Date : Jan. 25, 2017

Report Version : Rev. 01

Report No.: FR690802D


Report Template No.: BU5-FR15EWL AC MA Version 1.4




<Radiated Emission>

Y Plane for WLAN 5GHz 802.11a/ac VHT40/VHT80

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGZ3S00211 Page Number : D2 of D3
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01

Report No.: FR690802D


Report Template No.: BU5-FR15EWL AC MA Version 1.4



X Plane for WLAN 5GHz 802.11n HT20/HT40/ac VHT20 LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGZ3S00211 Page Number : D3 of D3
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01

Report No.: FR690802D

Report Template No.: BU5-FR15EWL AC MA Version 1.4