

Report No.: FR693034-02D

Setup Photographs

<Conducted Emission>




Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 1 of 5
Report Issued Date : May 26, 2017
Report Version : Rev. 01





Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 2 of 5
Report Issued Date : May 26, 2017
Report Version : Rev. 01




Report No.: FR693034-02D


<Radiated Emission>

Y Plane for 03CH11-HY

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 3 of 5
Report Issued Date : May 26, 2017
Report Version : Rev. 01

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 4 of 5
Report Issued Date : May 26, 2017
Report Version : Rev. 01


Report No.: FR693034-02D



Report No. : FR693034-02D

Y Plane for 03CH12-HY

HF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 5 of 5
Report Issued Date : May 26, 2017
Report Version : Rev. 01