



Report No. ATT-2016SZ0516846 - Page 9 of 24 -


#### 3 Internal Photos of the EUT









Report No. ATT-2016SZ0516846 - Page 10 of 24 -









Report No. ATT-2016SZ0516846 - Page 11 of 24 -








Report No. ATT-2016SZ0516846 - Page 12 of 24 -









Report No. ATT-2016SZ0516846 - Page 13 of 24 -








Report No. ATT-2016SZ0516846 - Page 14 of 24 -








Report No. ATT-2016SZ0516846 - Page 15 of 24 -








Report No. ATT-2016SZ0516846 - Page 16 of 24 -








Report No. ATT-2016SZ0516846 - Page 17 of 24 -








Report No. ATT-2016SZ0516846 - Page 18 of 24 -








Report No. ATT-2016SZ0516846 - Page 19 of 24 -








Report No. ATT-2016SZ0516846 - Page 20 of 24 -







Report No. ATT-2016SZ0516846 - Page 21 of 24 -







Report No. ATT-2016SZ0516846 - Page 22 of 24 -








Report No. ATT-2016SZ0516846 - Page 23 of 24 -







Report No. ATT-2016SZ0516846 - Page 24 of 24 -

