Model Difference

FCC ID: 2AIT8TS-90112BL

Model: TS-90110BL, TS-90112BL, TS-90113BL, TS-90115BL, TS-90118BL, TS-90210BL, TS-90118BL, TS-9018BL, TS-9 90212BL,TS-90215BL,TS-90218BL,TS-90310BL,TS-90312BL,TS-90101BL,TS-90121BL,TS-90152BL,TS-90228BL,TS-90512BL,TS-90510BL,TS-90512BL,TS-94110BL,TS-95110BL,TS-96110BL,TS-97110BL,TS-98110BL,TS-99110BL,TS-93112BL,TS-94112BL,TS-95112BL,TS-96112BL,TS-97112BL,TS-98112BL,TS-99112BL,TS-92115BL,TS-93115BL,TS-94115BL,TS-95115BL,TS-96115BL,TS-97115BL,TS-98115BL,TS-99115BL,TS-95210BL,TS-96210BL,TS-97210BL,TS-98210BL,TS-99210BL,TS-93212BL,TS-94212BL,TS-95212BL,TS-96212BL,TS-97212BL,TS-98212BL,TS-99212BL,TS-92215BL,TS-93215BL,TS-94215BL,TS-95215BL,TS-96215BL,TS-97215BL,TS-98215BL,TS-99215BL,TS-90108BL,TS-91108BL,TS-92108BL,TS-93108BL,TS-94108BL,TS-95108BL,TS-96108BL,TS-97108BL,TS-98108BL,TS-99108BL,TS-90208BL,TS-91208BL,TS-92208BL,TS-93208BL,TS-95208BL,TS-96208BL,TS-97208BL,TS-98208BL,TS-99208BL,QS-1021,QS-1023,QS-1051,QS-1251,QS-1052,QS-1252,QS-1551,QS-1552,QS-1062,QS-1063,QS-1066,QS-1067,QS-1068,QS-861,QS-862,QS-863,QS-865,QS-866, QS-867,QS-868,QS-869,QS-870,QS-871,QS-872,QS-873,QS-1260,QS-1261,QS-1262,QS-1263, QS-1265,QS-1266,QS-1267,QS-1268,QS-1269,QS-1270,QS-1271,QS-1272,QS-1273,QS-1275, QS-1276,QS-1277,QS-1278,QS-1279,QS-1561,QS-1562,QS-1563,QS-1565,QS-1566,QS-1567, QS-1568,QS-1569,QS-1570,QS-1571,QS-1572,QS-1573,QS-1058,QS-1057,QS-1256,QS-1257, QS-1553,QS-1558,QS-8261,QS-8262,QS-8263,QS-8265,QS-8266,QS-8267,QS-8268,QS-8269, QS-10261,QS-10262,QS-10263,QS-10265,QS-10266,QS-10267,QS-10268,QS-10269,QS-10270, QS-10271,QS-12260,QS-12261,QS-12262,QS-12263,QS-12265,QS-12266,QS-12267,QS-12268, QS-12269,QS-12270,QS-15261,QS-15262,QS-15263,QS-15265,QS-15266,QS-15267,QS-15268, QS-15269,QS-15270,QS-15271,QS-15272,QS-15273

All the model are the same circuit and RF module, except model names.

Regards

Sincerely

Client's signature:

Client's name / title : Deliu Tan /Manager

Contact information / address: 5F, NO.89 JIANSHE ROAD (N.) HUADU, GUANGZHOU,

CHINA