

180889_b.jpg: MGB2-L2-MLI-U-Y0000-BJ-156392, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Report Number:
 F180889E1

 Date of issue:
 08/24/2018
 Order Number:
 18-110889

 page 1 of 7
 18-110889
 18-110889






180889_a.jpg: MGB2-L2-MLI-U-Y0000-BJ-156392, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Report Number:
 F180889E1

 Date of issue:
 08/24/2018
 Order Number:
 18-110889

 page 2 of 7
 page 2 of 7





180889_c.jpg: MGB2-L2-MLI-U-Y0000-BJ-156392, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Report Number:
 F180889E1


 Date of issue:
 08/24/2018
 Order Number:
 18-110889

page 3 of 7



page 4 of 7


Annex A Test setup photographs



180889_d.jpg: MGB2-L2-MLI-U-Y0000-BJ-156392, test set-up fully anechoic chamber

Examiner: Thomas KÜHN Date of issue: 08/24/2018 F180889E1 18-110889






180889_e.jpg: MGB2-L2-MLI-U-Y0000-BJ-156392, test set-up outdoor test site

 Examiner:
 Thomas KÜHN
 Report Number:
 F180889E1

 Date of issue:
 08/24/2018
 Order Number:
 18-110889

 page 5 of 7
 7





180889_f.jpg: MGB2-L2-MLI-U-Y0000-BJ-156392, test set-up open area test site

 Examiner:
 Thomas KÜHN
 Report Number:
 F180889E1

 Date of issue:
 08/24/2018
 Order Number:
 18-110889

 page 6 of 7
 7





180889_g.jpg: MGB2-L2-MLI-U-Y0000-BJ-156392, test set-up shielded chamber

 Examiner:
 Thomas KÜHN
 Report Number:
 F180889E1

 Date of issue:
 08/24/2018
 Order Number:
 18-110889

 page 7 of 7