Test report No.
 : 11826181S

 Page
 : 35 of 39

 Issued date
 : July 19, 2017


 FCC ID
 : 2AJE9MR-2400MA


### **APPENDIX 3: Photographs of test setup**

### **Radiated Spurious Emission**


#### Patch antenna








Above 1 GHz






1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

: 11826181S Test report No. Page : 36 of 39 : July 19, 2017 : 2AJE9MR-2400MA Issued date FCC ID


### Monopole antenna


Below 1 GHz














1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

: 11826181S Test report No. Page : 37 of 39 : July 19, 2017 : 2AJE9MR-2400MA Issued date FCC ID

### **Bow-tie antenna**










1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

Test report No. : 11826181S
Page : 38 of 39
Issued date : July 19, 2017
FCC ID : 2AJE9MR-2400MA

# **Worst Case Position**




## UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401

Test report No. : 11826181S
Page : 39 of 39
Issued date : July 19, 2017
FCC ID : 2AJE9MR-2400MA



**End of Report** 

## UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone: +81 463 50 6400 Facsimile: +81 463 50 6401