


Appendix Test Setup Photo

Photo of radiated spurious emission






Report No.: TR-W1703-008 Page 1 of 4

ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 464-942

Report Form_01 (Rev.0) http://www.the-eng.co.kr

TEL: +82-31-727-8300 FAX: +82-31-746-0800








Report No.: TR-W1703-008 Page 2 of 4

ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 464-942


Report Form_01 (Rev.0)

TEL: +82-31-727-8300 FAX: +82-31-746-0800 http://www.the-eng.co.kr









Report No.: TR-W1703-008 Page 3 of 4

FAX: +82-31-746-0800

ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 464-942

TEL: +82-31-727-8300

Report Form_01 (Rev.0) http://www.the-eng.co.kr



Photo of AC power line conducted emission





AC power line conducted emissions_Rear



Report No.: TR-W1703-008 Page 4 of 4

ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 464-942

Report Form_01 (Rev.0)

TEL: +82-31-727-8300 FAX: +82-31-746-0800 http://www.the-eng.co.kr