Test report No.
 : 12311663H-A-R1

 Page
 : 22 of 24

 Issued date
 : August 28, 2018

 FCC ID
 : 2AKB8K68PB

## **APPENDIX 3: Photographs of test setup**

#### **Radiated Emission**




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 12311663H-A-R1
Page : 23 of 24
Issued date : August 28, 2018
FCC ID : 2AKB8K68PB

## **Worst Case Position**

BCM
Below 30MHz
X-axis
Above 30MHz
Horizontal:X-axis / Vertical:X-axis
X-axis



Y-axis



**Z**-axis




LF Antenna(ANL)
Below 30MHz
X-axis
Above 30MHz
Horizontal:Y-axis / Vertical:X-axis
X-axis



Y-axis

**Z**-axis



UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124


Test report No. : 12311663H-A-R1
Page : 24 of 24
Issued date : August 28, 2018
FCC ID : 2AKB8K68PB

## **Worst Case Position**

#### LF Antenna(ANB)

Below 30MHz
X-axis
Above 30MHz
Horizontal:X-axis / Vertical:Y-axis
X-axis







# **End of Report**

# UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124