Test report No.
 : 11624584H-C

 Page
 : 51 of 53

 Issued date
 : June 30, 2017

 FCC ID
 : 2AL4MDMS-W1

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

 Test report No.
 : 11624584H-C

 Page
 : 52 of 53

 Issued date
 : June 30, 2017

 FCC ID
 : 2AL4MDMS-W1

Radiated Spurious Emission




Photo 1





Photo 2


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 11624584H-C Page : 53 of 53 Issued date : June 30, 2017 FCC ID : 2AL4MDMS-W1

Worst Case Position
(Horizontal: X-axis / Vertical: X-axis)





Z-axis

End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile : +81 596 24 8124