Test report No.
 : 11873611H-B

 Page
 : 50 of 52

 Issued date
 : August 31, 2017

 FCC ID
 : 2AL4MP01

## **APPENDIX 3: Photographs of test setup**

## **Conducted Emission**




Photo 1



Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

 Test report No.
 : 11873611H-B

 Page
 : 51 of 52

 Issued date
 : August 31, 2017

 FCC ID
 : 2AL4MP01

## **Radiated Spurious Emission**




Photo 1





Photo 2


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 11873611H-B Page : 52 of 52 Issued date : August 31, 2017 FCC ID : 2AL4MP01

Worst Case Position
Above 1 GHz (Horizontal: X-axis/ Vertical: Z-axis) Below 1 GHz (Horizontal: X-axis/ Vertical: X-axis)







**End of Report** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile : +81 596 24 8124