Setup Photographs

<Conducted Emission>



Remote View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBL-1731 Page Number : 1 of 5
Report Issued Date : Jul. 17, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL MA Version 1.3

Report No. : FR730732-01C





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBL-1731 Page Number : 2 of 5
Report Issued Date : Jul. 17, 2017
Report Version : Rev. 01

Report No. : FR730732-01C

Report Template No.: BU5-FR15CWL MA Version 1.3


<Radiated Emission>

X Plane for Ant. 1

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBL-1731 Page Number : 3 of 5
Report Issued Date : Jul. 17, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL MA Version 1.3


Report No. : FR730732-01C

Z Plane for Ant. 2

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBL-1731 Page Number : 4 of 5
Report Issued Date : Jul. 17, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL MA Version 1.3

Report No. : FR730732-01C


CC RF Test Report Report No.: FR730732-01C

Y Plane for MIMO Ant. 1+2

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ALBL-1731 Page Number : 5 of 5
Report Issued Date : Jul. 17, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL MA Version 1.3