Test report No. : 12455993H-A-R1
Page : 49 of 51
Issued date : December 10, 2018
FCC ID : 2ALNEJO1MDW

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326Asama-cho, Ise-shi, Mie-ken516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 12455993H-A-R1
Page : 50 of 51
Issued date : December 10, 2018
FCC ID : 2ALNEJO1MDW

Radiated Spurious Emission




Photo 1





Photo 2


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 12455993H-A-R1
Page : 51 of 51
Issued date : December 10, 2018
FCC ID : 2ALNEJO1MDW

Worst Case Position (Horizontal: Y-axis/ Vertical: X-axis)







End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124