## 3. Internal Photograph of EUT

Model Name: BP39CN


Report No.: EP7O1301-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : 8 of 15
Report Issued Date : Mar. 19, 2018
Report Version : Rev. 01

Martal Name - DD000N


Report No.: EP7O1301-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : 9 of 15
Report Issued Date : Mar. 19, 2018
Report Version : Rev. 01



Report No.: EP7O1301-01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : 10 of 15 Report Issued Date : Mar. 19, 2018 Report Version : Rev. 01

Model Name: BP39CN


Report No.: EP7O1301-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : 11 of 15
Report Issued Date : Mar. 19, 2018
Report Version : Rev. 01

Model Name: BP39CN


Report No.: EP7O1301-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : 12 of 15
Report Issued Date : Mar. 19, 2018
Report Version : Rev. 01

Model Name: BP39CN


Report No.: EP7O1301-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : 13 of 15
Report Issued Date : Mar. 19, 2018
Report Version : Rev. 01




Report No.: EP7O1301-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : 14 of 15
Report Issued Date : Mar. 19, 2018
Report Version : Rev. 01





SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number : 15 of 15 Report Issued Date : Mar. 19, 2018 Report Version : Rev. 01

Report No.: EP7O1301-01