


Appendix A. Test Photos

Conducted Test



Conducted Test



SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A1 of A6

Report No.: FR5O1328

Report Version : Rev. 01



FCC Test Report Report No.: FR501328




SPORTON INTERNATIONAL INC. Page No. : A2 of A6
TEL: 886-3-3273456 Report Version : Rev. 01

FAX: 886-3-3270973






Report No.: FR5O1328



Radiated below 1GHz Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A3 of A6

Report Version : Rev. 01



FCC Test Report

Radiated below 1GHz Test

Report No.: FR5O1328

: A4 of A6


: Rev. 01

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-3273456 Report Version


FAX: 886-3-3270973



FCC Test Report No.: FR501328



Radiated above 1GHz Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A5 of A6

Report Version : Rev. 01




FCC Test Report

Report No. : FR5O1328

: A6 of A6

: Rev. 01



SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-3273456 Report Version

FAX: 886-3-3270973