

November 26th, 2009

Equipment Autorisation Division Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

FCC ID:T5M8900V2

Tune-up procedure

All devices falling under T5M8900V2 do not have any tune-up procedure. Furthemore, our WWAN device doesn't permit the power/frequency tune-up.

Regards,

Pierre Olivier
V.-P. Engineering
p.olivier@daptech.com

DAP Technologies LTD. 875, Blvd. Charest West, # 200 Quebec, Qc. Canada, G1N 2C9

Phone: Fax: +1 418 681 7833 +1 418 681 7734

www.daptech.com