## Appendix A. Photographs of EUT

Please refer to Sporton report number EP170707 as below.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 Page Number : A1 of A1
Report Issued Date : Oct. 04, 2011
Report Version : Rev. 01

Report No.: FR170707B

## 1. External Photograph of EUT

Brand Name: DAP / Model Name: 9000WBWZV1 / Marketing Name: M9010

Report No.: EP170707



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 1 of 19
Report Issued Date : Oct. 04, 2011
Report Version : Rev. 01

Report No.: EP170707



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 2 of 19
Report Issued Date : Oct. 04, 2011
Report Version : Rev. 01

## 2. Photograph of Accessory

Brand Name: DAP / Model Name: 9000WBWZV1 / Marketing Name: M9010

Report No.: EP170707

**List of Accessory:** 

List of Accessory:		
Specification of Accessory		
AC Adapter	Brand Name	CINCON ELECTRONICS
	Model Name	TRG36A15 12E03
Battery 1	Brand Name	DAP
	Model Name	VE026-8034
Battery 2	Brand Name	DAP
	Model Name	VE026-8035
LCD Panel	Brand Name	SGD
	Model Name	GNTW70NNBA1E0
Camera 1	Brand Name	DEMARREN
	Model Name	Q5M03A
WWAN Module	Brand Name	Sierra Wireless
	Model Name	MC8355
WLAN Module	Brand Name	Summit Data Communications
	Model Name	SDC-PE15N
Bluetooth Module	Brand Name	Bluegiga
	Model Name	WT21-A
Zigbee Module	Brand Name	Atmel
	Model Name	ATmega128RFA1
Power Cord 1	Brand Name	QUAIL
	Model Name	1062.079(NAM032)
Power Cord 2	Brand Name	QUAIL
	Model Name	8002.079(NAM033)
Power Cord 3	Brand Name	QUAIL
	Model Name	9657.079(NAM034)

**Remark:** For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 3 of 19
Report Issued Date : Oct. 04, 2011

Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 4 of 19
Report Issued Date : Oct. 04, 2011
Report Version : Rev. 01


Report No.: EP170707



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 5 of 19
Report Issued Date : Oct. 04, 2011

Report Version : Rev. 01

Report No.: EP170707



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 6 of 19
Report Issued Date : Oct. 04, 2011
Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1

Page Number

: 7 of 19

Report Issued Date : Oct. 04, 2011

Report Version


: Rev. 01

Report No.: EP170707

## 3. Internal Photograph of EUT

Brand Name: DAP / Model Name: 9000WBWZV1 / Marketing Name: M9010

Report No.: EP170707



TEL: 886-3-327-3456

FAX: 886-3-328-4978


FCC ID: T5M9000WBWZV1

IC: 4609A-9000WBWZV1

Page Number : 8 of 19
Report Issued Date : Oct. 04, 2011
Report Version : Rev. 01



Brand Name: DAP / Model Name: 9000WBWZV1 / Marketing Name: M9010



TEL: 886-3-327-3456

FAX: 886-3-328-4978


FCC ID: T5M9000WBWZV1

IC: 4609A-9000WBWZV1

Page Number : 9 of 19
Report Issued Date : Oct. 04, 2011
Report Version : Rev. 01




Report No.: EP170707



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 10 of 19
Report Issued Date : Oct. 04, 2011
Report Version : Rev. 01



Report No.: EP170707




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1

Page Number : 11 of 19 Report Issued Date : Oct. 04, 2011 : Rev. 01 Report Version



Report No.: EP170707




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1

Page Number : 12 of 19 Report Issued Date : Oct. 04, 2011 Report Version : Rev. 01




Report No.: EP170707



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1


Page Number : 13 of 19 Report Issued Date : Oct. 04, 2011 Report Version : Rev. 01



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 14 of 19
Report Issued Date : Oct. 04, 2011
Report Version : Rev. 01

Report No.: EP170707



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 15 of 19
Report Issued Date : Oct. 04, 2011
Report Version : Rev. 01




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 16 of 19
Report Issued Date : Oct. 04, 2011
Report Version : Rev. 01

Report No.: EP170707



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1 Page Number : 17 of 19
Report Issued Date : Oct. 04, 2011
Report Version : Rev. 01



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1

: 18 of 19 Page Number Report Issued Date : Oct. 04, 2011

Report Version : Rev. 01



Report No.: EP170707



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: T5M9000WBWZV1 IC: 4609A-9000WBWZV1

Page Number : 19 of 19 Report Issued Date : Oct. 04, 2011 Report Version : Rev. 01