Test report No. : 32LE0115-HO-01-B-R1

 Page
 : 17 of 19

 Issued date
 : October 29, 2012

 Revised date
 : November 9, 2012

 FCC ID
 : T82-TW800R

APPENDIX 3: Photographs of test setup

Radiated Emission



Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 32LE0115-HO-01-B-R1

 Page
 : 18 of 19

 Issued date
 : October 29, 2012

 Revised date
 : November 9, 2012

 FCC ID
 : T82-TW800R

Worst Case Position (Horizontal: Z-axis/ Vertical: Y-axis)





Y-axis



Z-axis



Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

: 32LE0115-HO-01-B-R1 Test report No.

Page : 19 of 19 Issued date : October 29, 2012 Revised date : November 9, 2012 : T82-TW800R FCC ID

Worst Case Position (Horizontal: ANT2 X02-axis/ Vertical: ANT2 X01 -axis)



ANT2 X01-axis





ANT2 X02-axis



ANT1 Y01-axis




ANT2 Y01-axis



ANT1 Y02-axis



ANT2 Y02-axis



End of Report

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 : +81 596 24 8124 Facsimile