

July 28, 2005

ATTN: Reviewing Engineer
FEDERAL COMMUNICATIONS COMMISSION
7435 Oakland Mills Road
Columbia MD 21046

RE: TUNE-UP PROCEDURE FOR R5000-L-4.9, FCC ID TIG R5000-L-49

To Whom It May Concern:

We, the undersigned, state that the equipment known as the INFINET R5000-L-4.9 wireless router, FCC ID TIG R5000-L-49, has no field-adjustable hardware adjustment points. All adjustments and configuration changes are made via software, as described in the user manual for this equipment. Therefore, we are not submitting a separate tune-up procedure for this equipment.

Please contact me if there is any information you may need.

Sincerely,

Hay Weber
Gary Weber
Vice President

CONTINENTAL WIRELESS, INC.