


## ATTACHMENT F.

- INTERNAL PHOTOS -

Report No.: HCTR1005FR16 1/35








Report No.: HCTR1005FR16 2/35







Report No.: HCTR1005FR16 3/35








Report No.: HCTR1005FR16 4/35






Report No.: HCTR1005FR16 5/35








Report No.: HCTR1005FR16 6/35







Report No.: HCTR1005FR16 7/35





Report No.: HCTR1005FR16 8 / 35





Report No.: HCTR1005FR16 9/35




## FCC ID: TQ8-AVN-700MDA / IC: 5074A-AVN700MDCA



Report No.: HCTR1005FR16 10 / 35






Report No.: HCTR1005FR16 11/35






Report No.: HCTR1005FR16 12/35









Report No.: HCTR1005FR16 13/35





Report No.: HCTR1005FR16 14/35







Report No.: HCTR1005FR16 15/35







Report No.: HCTR1005FR16 16/35






Report No.: HCTR1005FR16 17/35








Report No.: HCTR1005FR16 18 / 35







Report No.: HCTR1005FR16 19 / 35









Report No.: HCTR1005FR16 20 / 35







Report No.: HCTR1005FR16 21/35






Report No.: HCTR1005FR16 22 / 35





Report No.: HCTR1005FR16 23 / 35







Report No.: HCTR1005FR16 24 / 35









Report No.: HCTR1005FR16 25 / 35








Report No.: HCTR1005FR16 26 / 35





Report No.: HCTR1005FR16 27 / 35






Report No.: HCTR1005FR16 28 / 35









Report No.: HCTR1005FR16 29 / 35









Report No.: HCTR1005FR16 30 / 35





Report No.: HCTR1005FR16 31/35






Report No.: HCTR1005FR16 32/35







Report No.: HCTR1005FR16 33 / 35





Report No.: HCTR1005FR16 34/35





Report No.: HCTR1005FR16 35 / 35