


ATTACHMENT F.

- INTERNAL PHOTOS -


Report No.: HCTR0910FR07 1/14








Report No.: HCTR0910FR07 2/14









Report No.: HCTR0910FR07 3/14








Report No.: HCTR0910FR07 4/14








Report No.: HCTR0910FR07 5/14









Report No.: HCTR0910FR07 6/14









Report No.: HCTR0910FR07 7/14









Report No.: HCTR0910FR07 8/14









Report No.: HCTR0910FR07 9/14








Report No.: HCTR0910FR07 10/14









Report No.: HCTR0910FR07 11/14




FCC ID: TQ8-PA760VQ/IC: 5074A-PA760VQ



Report No.: HCTR0910FR07 12/14








Report No.: HCTR0910FR07 13/14







Report No.: HCTR0910FR07 14/14