Test report no.: 1-0794-01-04/08-A




## 6 Photographs of the Test Set-up

Photo No. 1



Photo No. 2



2009-03-19 Page 38 of 55

## CETECOM ICT Services GmbH

Test report no.: 1-0794-01-04/08-A



Photo No. 3



2009-03-19 Page 39 of 55

## **CETECOM ICT Services GmbH**

Test report no.: 1-0794-01-04/08-A



Photo No. 4




Photo No. 5



2009-03-19 Page 40 of 55

## CETECOM ICT Services GmbH

Test report no.: 1-0794-01-04/08-A



Photo No. 4



Remark: modification was done by means of using ferrites on the main-lead

2009-03-19 Page 41 of 55