External photographs of equipment under test





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053

Phone/Fax: (913) 837-3214 Revision 1

Mikrotikls SIA

Model: RB962UiGS-5HacT2HnT-US


Test #: 160514b


Test to: 47CFR, 15.247, 15.407, RSS-247 File: RB962UiGS5HacT2HnT ExtPho

S/N: 673705E3318F/603 FCC: TV7RB962-5ACT2NT

IC: 7442A-9625AC Date: August 15, 2016

Page 1 of 3





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA

Model: RB962UiGS-5HacT2HnT-US


Test #: 160514b

Test to: 47CFR, 15.247, 15.407, RSS-247 File: RB962UiGS5HacT2HnT ExtPho

S/N: 673705E3318F/603 FCC: TV7RB962-5ACT2NT

IC: 7442A-9625AC Date: August 15, 2016

Page 2 of 3





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Mikrotikls SIA

Model: RB962UiGS-5HacT2HnT-US

Test #: 160514b

Test to: 47CFR, 15.247, 15.407, RSS-247 File: RB962UiGS5HacT2HnT ExtPho

S/N: 673705E3318F/603 FCC: TV7RB962-5ACT2NT

IC: 7442A-9625AC Date: August 15, 2016

Page 3 of 3