
Test setup photographs





Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214 Revision 1

Mikrotikls SIA

Model: RB962UiGS-5HacT2HnT-US

Test #: 160514b

Test to: 47CFR, 15.247, 15.407, RSS-247 File: RB962UiGS5HacT2HnT TSup

S/N: 673705E3318F/603

FCC: TV7RB962-5ACT2NT

IC: 7442A-9625AC Date: August 15, 2016

Page 1 of 6





Mikrotikls SIA S/N: 673705E3318F/603

Model: RB962UiGS-5HacT2HnT-US

Test #: 160514b

Test to: 47CFR, 15.247, 15.407, RSS-247 File: RB962UiGS5HacT2HnT TSup

FCC: TV7RB962-5ACT2NT

IC: 7442A-9625AC Date: August 15, 2016

Page 2 of 6



Mikrotikls SIA

Model: RB962UiGS-5HacT2HnT-US

Test #: 160514b


Test to: 47CFR, 15.247, 15.407, RSS-247 File: RB962UiGS5HacT2HnT TSup

S/N: 673705E3318F/603

FCC: TV7RB962-5ACT2NT

IC: 7442A-9625AC Date: August 15, 2016

Page 3 of 6



Mikrotikls SIA

Model: RB962UiGS-5HacT2HnT-US

Test #: 160514b

Test to: 47CFR, 15.247, 15.407, RSS-247 File: RB962UiGS5HacT2HnT TSup

S/N: 673705E3318F/603

FCC: TV7RB962-5ACT2NT

IC: 7442A-9625AC Date: August 15, 2016

Page 4 of 6



Mikrotikls SIA S Model: RB962UiGS-5HacT2HnT-US

Test #: 160514b

Test to: 47CFR, 15.247, 15.407, RSS-247 File: RB962UiGS5HacT2HnT TSup

S/N: 673705E3318F/603

FCC: TV7RB962-5ACT2NT

IC: 7442A-9625AC Date: August 15, 2016

Page 5 of 6



Mikrotikls SIA

Model: RB962UiGS-5HacT2HnT-US

Test #: 160514b

Test to: 47CFR, 15.247, 15.407, RSS-247 File: RB962UiGS5HacT2HnT TSup

S/N: 673705E3318F/603

FCC: TV7RB962-5ACT2NT

IC: 7442A-9625AC Date: August 15, 2016

Page 6 of 6