

Appendix D. Product Photos

<Sample 1>





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8188CE Page Number : D1 of D2
Report Issued Date : Mar. 23, 2011
Report Version : Rev. 01

Report No.: FA020501-25





<Sample2>








Report No.: FA020501-25

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8188CE Page Number : D2 of D2
Report Issued Date : Mar. 23, 2011
Report Version : Rev. 01



Appendix E. Test Setup Photos



Bottom of the DUT with Phantom 0 cm Gap for (Sample 1)

Bottom of the DUT with Phantom 0 cm Gap for (Sample 2)

Report No.: FA020501-25

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8188CE Page Number : E1 of E1 Report Issued Date: Mar. 23, 2011

Report Version : Rev. 01