



Appendix D. Product Photos





Report No.: FA020501-31



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8188CE Page Number : D1 of D1
Report Issued Date : Sep. 08, 2011
Report Version : Rev. 02



Report No.: FA020501-31

Appendix E. Test Setup Photos




Horizontal Up with Phantom 1.4 cm Gap (Main Antenna Port)



Horizontal Down with Phantom 1.4 cm Gap (Main Antenna Port)



Horizontal Down with Phantom 1.4 cm Gap (Aux Antenna Port)



Vertical Up with Phantom 1.4 cm Gap (Main Antenna Port)



Vertical Down with Phantom 1.4 cm Gap (Main Antenna Port)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8188CE Page Number : E1 of E1
Report Issued Date : Sep. 08, 2011
Report Version : Rev. 02