

Appendix D. SAR Test Setup Photos


<Chain 1>




Report No.: FA332724-05

Front, Test Separation 0.8 cm











Left Side, Test Separation 0.8 cm



Top Side, Test Separation 0.8 cm




Bottom Side, Test Separation 0.8 cm

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : D1 of D3
Report Issued Date : Jul. 17, 2013
Report Version : Rev. 01



<Chain 1+2>




Front, Test Separation 0.8 cm




Report No.: FA332724-05


Back, Test Separation 0.8 cm




Right Side-1, Test Separation 0.8 cm



Right Side-2, Test Separation 0.8 cm



Left Side-1, Test Separation 0.8 cm




Left Side-2, Test Separation 0.8 cm

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : D2 of D3
Report Issued Date : Jul. 17, 2013
Report Version : Rev. 01



FCC SAR Test Report





Report No.: FA332724-05

Top Side, Test Separation 0.8 cm

Bottom Side, Test Separation 0.8 cm

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8192EEBT Page Number : D3 of D3
Report Issued Date : Jul. 17, 2013
Report Version : Rev. 01