



Appendix D. Product Photos





Report No.: FA020501-31



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8188CE Page Number : D1 of D1
Report Issued Date : Aug. 15, 2011
Report Version : Rev. 01



Report No.: FA020501-31

Appendix E. **Test Setup Photos**




Horizontal Up with Phantom 1.4 mm Gap (DUT with Antenna 1)




Horizontal Down with Phantom 1.4 mm Gap (DUT with Antenna 1)



Horizontal Down with Phantom 1.4 mm Gap (DUT with Antenna 2)



Vertical Up with Phantom 1.4 mm Gap (DUT with Antenna 1)



Vertical Down with Phantom 1.4 mm Gap (DUT with Antenna 1)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8188CE Page Number : E1 of E1 Report Issued Date: Aug. 15, 2011

: Rev. 01 Report Version