



Report No. : FA322105-05


Appendix D. SAR Test Setup Photos




Top Side of the DUT with Phantom 0.5 cm Gap




Bottom of the DUT with Phantom 0.5 cm Gap



Front of the DUT with Phantom 0.5 cm Gap



Back of the DUT with Phantom 0.5 cm Gap



Right Side of the DUT with Phantom 0.5 cm Gap



Left Side of the DUT with Phantom 0.5 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BE Page Number : D1 of D1
Report Issued Date : May 17, 2013
Report Version : Rev. 01