1. Photograph of the EUT

EUT: 802.11b/g/n RTL8723BS Combo module (Brand Name: REALTEK / Model Name: RTL8723BS)

Report No.: EP6N2509




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 1 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01

EUT: 802.11b/g/n RTL8723BS Combo module

Report No.: EP6N2509

(Brand Name: REALTEK / Model Name: RTL8723BS)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 2 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01

2. External Photograph of the Host


Host: (Brand Name: UNICOM / Model Name: U-BPCIB000, U-BPCIB001)

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 3 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01

Host: (Brand Name: UNICOM / Model Name: U-BPCIB000, U-BPCIB001)



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 4 of 32 Report Issued Date : Jan. 25, 2017 Report Version : Rev. 01

Heate /Durand Marson HMICOM / Madel Marson H DDCIDOO H DDCIDOO4

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 5 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 6 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 7 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 8 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 9 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 10 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 11 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 12 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 13 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01

Report No.: EP2D0508-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 14 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01

3. **Photograph of Accessory for the Host**

Host: (Brand Name: UNICOM / Model Name: U-BPCIB000, U-BPCIB001)

Report No.: EP2D0508-01

List of Accessory for Host:


Specification of Accessory		
IAC Adapter	Brand Name	FSP
	Model Name	FSP060-DIBAN2

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 15 of 32 Report Issued Date : Jan. 25, 2017

Report Version : Rev. 01



Host: (Brand Name: UNICOM / Model Name: U-BPCIB000, U-BPCIB001)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 16 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01

Report No.: EP2D0508-01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723BS Page Number : 17 of 32
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01