


Appendix D. Product Photos




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8188EE Page Number : D1 of D1
Report Issued Date : May 21, 2012
Report Version : Rev. 01

Report No.: FA211949-02




Report No.: FA211949-02


Appendix E. Test Setup Photos



Front of the DUT with Phantom 1.6 cm Gap


Back of the DUT with Phantom 1.6 cm Gap






Right Side of the DUT with Phantom 1.6 cm Gap

Left Side of the DUT with Phantom 1.6 cm Gap





Top Side of the DUT with Phantom 1.6 cm Gap Bottom Side of the DUT with Phantom 1.6 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8188EE Page Number : E1 of E1 Report Issued Date: May 21, 2012 Report Version : Rev. 01