


Appendix D. Product Photos




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8188CEBT IC: 6317A-RTL8188CEBT Page Number : D1 of D2
Report Issued Date : Jun. 24, 2010
Report Version : Rev. 01

Report No.: FA022402-05

FCC/IC SAR Test Report

Antenna Location:



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8188CEBT IC: 6317A-RTL8188CEBT D2 of D2

Report No.: FA022402-05

Report Issued Date : Jun. 24, 2010 Report Version : Rev. 01



Appendix E. Test Setup Photos



Bottom of the Laptop with Phantom 0 cm Gap

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2RTL8188CEBT IC: 6317A-RTL8188CEBT Page Number : E1 of E1
Report Issued Date : Jun. 24, 2010
Report Version : Rev. 01

Report No.: FA022402-05