


Report No. : FA1N2318-01

## Appendix D. Product Photos



WLAN Antenna <Tx / Rx>

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723AE Page Number : D1 of D2
Report Issued Date : Feb. 15, 2012
Report Version : Rev. 01



## Appendix E. Test Setup Photos




Front of the DUT with Phantom 1.7 cm Gap



Report No.: FA1N2318-01


Back of the DUT with Phantom 1.7 cm Gap




Right Side of the DUT with Phantom 1.7 cm Gap



Left Side of the DUT with Phantom 1.7 cm Gap



Top Side of the DUT with Phantom 1.7 cm Gap



Bottom Side of the DUT with Phantom 1.7 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: TX2-RTL8723AE Page Number : E1 of E1 Report Issued Date: Feb. 15, 2012 Report Version : Rev. 01