

Date: February 22, 2010

Federal Communications Commission 7435 Oakland Mills Road, Colombia, MD 21046

RFID Function Disability Declaration

We hereby state that RFID function of the following equipment cannot be activated in the United States...

The RFID function of HIY02 is equipped the card-mode, however, Reader/Writer mode is not equipped. In the case of card-mode only, there is no carrier wave output by the unit itself at any time or place, so no interference is transmitted within North America.

FCC ID: TYKNX6590 Model: CDMA HIY02

Please contact us if you have any question regarding above.

Signature:

Casio Hitachi Mobile Communications Co., Ltd. 2-229-1, Sakuragaoka, Higashiyamato-shi Tokyo, Japan

TEL/FAX: +81-42-516-2184 / +81-42-516-2505