

Report No.: FA0N0835

## Appendix D. Product Photos




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570 Page Number : D1 of D2
Report Issued Date : Feb. 01, 2011
Report Version : Rev. 02



Report No.: FA0N0835

## **Antenna Location:**




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570 Page Number : D2 of D2
Report Issued Date : Feb. 01, 2011
Report Version : Rev. 02



## Report No.: FA0N0835


## Appendix E. **Test Setup Photos**



**Right Cheek** 




**Right Tilted** 



Left Cheek



**Left Tilted** 



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570

Page Number : E1 of E1 Report Issued Date: Feb. 01, 2011 Report Version : Rev. 02