1. External Photograph of EUT

Brand Name: OPEN MOBILE\PUBLIC MOBILE / Model Name: M570

Report No.: EP0N0835-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570A Page Number : 1 of 22
Report Issued Date : May 26, 2011
Report Version : Rev. 01

Report No.: EP0N0835-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570A Page Number : 2 of 22 Report Issued Date : May 26, 2011

Report Version : Rev. 01



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570A Page Number : 3 of 22
Report Issued Date : May 26, 2011
Report Version : Rev. 01



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570A Page Number : 4 of 22
Report Issued Date : May 26, 2011
Report Version : Rev. 01



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570A Page Number : 5 of 22
Report Issued Date : May 26, 2011
Report Version : Rev. 01



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570A Page Number : 6 of 22
Report Issued Date : May 26, 2011
Report Version : Rev. 01



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570A Page Number : 7 of 22
Report Issued Date : May 26, 2011
Report Version : Rev. 01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570A

: 8 of 22 Page Number

Report Issued Date : May 26, 2011 Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: OPEN MOBILE\PUBLIC MOBILE / Model Name: M570

Report No.: EP0N0835-01

List of Accessory:

Specification of Accessory		
AC Adapter	Brand Name	BI
	Model Name	BI05-050050-BdU
Battery	Model Name	M560
USB Cable	Signal Line	1meter, non-shielded cable, w/o ferrite core

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570A Page Number : 9 of 22
Report Issued Date : May 26, 2011
Report Version : Rev. 01


Report No.: EP0N0835-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570A Page Number : 10 of 22
Report Issued Date : May 26, 2011

Report Version : Rev. 01

Report No.: EP0N0835-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570A Page Number : 11 of 22
Report Issued Date : May 26, 2011
Report Version : Rev. 01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570A

: 12 of 22 Page Number Report Issued Date : May 26, 2011 : Rev. 01

Report Version

Report No.: EP0N0835-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570A Page Number : 13 of 22
Report Issued Date : May 26, 2011
Report Version : Rev. 01

Report No.: EP0N0835-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570A Page Number : 14 of 22
Report Issued Date : May 26, 2011
Report Version : Rev. 01

Report No.: EP0N0835-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570A Page Number : 15 of 22
Report Issued Date : May 26, 2011
Report Version : Rev. 01

Report No.: EP0N0835-01



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570A Page Number : 16 of 22
Report Issued Date : May 26, 2011

Report Version : Rev. 01