

Appendix D. Internal Photographs

View of Inside




Report no. ETLE070307.133, Page D1 of D15




Appendix D. Internal Photographs

Top side view of main board



Report no. ETLE070307.133, Page D2 of D15


Bottom side view of main board



Report no. ETLE070307.133, Page D3 of D15




Top side view of power board



Report no. ETLE070307.133, Page D4 of D15




Bottom side view of power board



Report no. ETLE070307.133, Page D5 of D15



Top side view of front board



Report no. ETLE070307.133, Page D6 of D15




Bottom side view of front board




Report no. ETLE070307.133, Page D7 of D15

Top side view of sub board



Report no. ETLE070307.133, Page D8 of D15

Bottom side view of sub board




Report no. ETLE070307.133, Page D9 of D15



Tuner





Report no. ETLE070307.133, Page D10 of D15




Top side view of tuner board



Report no. ETLE070307.133, Page D11 of D15




Bottom side view of tuner board




Report no. ETLE070307.133, Page D12 of D15



RF modulator






Report no. ETLE070307.133, Page D13 of D15



Top side view of RF modulator board




Report no. ETLE070307.133, Page D14 of D15

ETLQP-21-F22-0



Bottom side view of RF modulator board



Report no. ETLE070307.133, Page D15 of D15

ETLQP-21-F22-0