



ATTACHMENT F.

- INTERNAL PHOTOS -

Report No.: HCTR1007FR30 1/23







Report No.: HCTR1007FR30 2/23







Report No.: HCTR1007FR30 3/23







Report No.: HCTR1007FR30 4/23







Report No.: HCTR1007FR30 5/23








Report No.: HCTR1007FR30 6/23





(NMS BOARD_1)




Report No.: HCTR1007FR30 7/23






(NMS BOARD_2)



Report No.: HCTR1007FR30 8/23








Report No.: HCTR1007FR30 9/23










Report No.: HCTR1007FR30 10/23





(TX Converter_1)




Report No.: HCTR1007FR30 11/23





(TX Converter_2)



Report No.: HCTR1007FR30 12/23








Report No.: HCTR1007FR30 13/23





(Ethernet Board_1)



Report No.: HCTR1007FR30 14/23










Report No.: HCTR1007FR30 15/23





(HPA)



Report No.: HCTR1007FR30 16/23





(IO Board_1)




Report No.: HCTR1007FR30 17/23






(LED_1)



Report No.: HCTR1007FR30 18/23








Report No.: HCTR1007FR30 19/23





(PSU_1)




Report No.: HCTR1007FR30 20/23





(PSU_2)



Report No.: HCTR1007FR30 21/23





(PSU_3)




Report No.: HCTR1007FR30 22/23





(PSU_4)



Report No.: HCTR1007FR30 23/23