



100984_e.jpg: EMP-7601 top view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F100984E2

 Date of issue:
 02 September 2010
 Order Number:
 100984
 page 1 of 8






100984_f.jpg: EMP-7601 bottom view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F100984E2

 Date of issue:
 02 September 2010
 Order Number:
 100984
 page 2 of 8






100984_d.jpg: BAT300-Rail FCC (Host), internal view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F100984E2

 Date of issue:
 02 September 2010
 Order Number:
 100984
 page 3 of 8






100984_g.jpg: BAT300-Rail FCC (Host), PCB 1, top view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F100984E2

 Date of issue:
 02 September 2010
 Order Number:
 100984
 page 4 of 8






100984_h.jpg: BAT300-Rail FCC (Host), PCB 1, bottom view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F100984E2

 Date of issue:
 02 September 2010
 Order Number:
 100984
 page 5 of 8






100984_j.jpg: BAT300-Rail FCC (Host), PCB 2, top view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F100984E2

 Date of issue:
 02 September 2010
 Order Number:
 100984
 page 6 of 8





100984_i.jpg: BAT300-Rail FCC (Host), PCB 2, bottom view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F100984E2

 Date of issue:
 02 September 2010
 Order Number:
 100984
 page 7 of 8





100984_p.jpg: BAT300-F FCC (Host), internal view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F100984E2

 Date of issue:
 02 September 2010
 Order Number:
 100984
 page 8 of 8