

Report No.: FR2O0211

Appendix A. Test Photos

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01





1 Photographs of Conducted Emissions Test Configuration

Mode 1



Report No.: FR2O0211

FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01





Report No.: FR2O0211



SIDE VIEW


SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01





2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



Report No.: FR2O0211

FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A4 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01



FCC RADIO TEST REPORT


For radiated emissions 30MHz~1GHz

Mode 1



Report No.: FR2O0211

FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A6


Report Version : Rev. 01



FCC RADIO TEST REPORT


For radiated emissions above 1GHz





Report No.: FR2O0211

FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. : A6 of A6
TEL: 886-3-327-3456 : Report Version : Rev. 01