Test report No. : 10636726H-B-R1

 Page
 : 54 of 56

 Issued date
 : February 20, 2015

 Revised date
 : March 5, 2015

 FCC ID
 : UCE314062A

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10636726H-B-R1

Page : 55 of 56

Issued date : February 20, 2015 Revised date : March 5, 2015 FCC ID : UCE314062A

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

: 10636726H-B-R1 Test report No.

Page : 56 of 56 **Issued date** : February 20, 2015 Revised date : March 5, 2015 FCC ID : UCE314062A

Worst Case Position
(Above 1GHz, Horizontal: X-axis/ Vertical: Z-axis) (Below 1GHz, Horizontal: X-axis/ Vertical: X-axis)







End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

: +81 596 24 8999 Telephone : +81 596 24 8124 Facsimile