Test report No. : 10636726H-D-R2

Page : 89 of 90

Issued date : February 20, 2015
Revised date : March 17, 2015
FCC ID : UCE314062A

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10636726H-D-R2


 Page
 : 90 of 90

 Issued date
 : February 20, 2015

 Revised date
 : March 17, 2015

 FCC ID
 : UCE314062A

Worst Case Position (Horizontal: X-axis/ Vertical: Z-axis)







End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124