Test report No. : 10636726H-C-R1
Page : 103 of 105
Issued date : February 20, 2015
Revised date : March 5, 2015
FCC ID : UCE314062A

APPENDIX 3: Photographs of test setup

Conducted Spurious Emission



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10636726H-C-R1
Page : 104 of 105
Issued date : February 20, 2015
Revised date : March 5, 2015
FCC ID : UCE314062A

Radiated Spurious Emission



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10636726H-C-R1
Page : 105 of 105
Issued date : February 20, 2015
Revised date : March 5, 2015
FCC ID : UCE314062A

<u>Worst Case Position</u> Horizontal: Y-axis/ Vertical: Y-axis







End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124