Test report No. : 10636726H-G-R3 : 25 of 28

Page

: February 20, 2015 : March 10, 2015 : UCE314062A **Issued date** Revised date FCC ID

APPENDIX 3: Photographs of test setup

Conducted emission




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10636726H-G-R3

Page : 26 of 28

 Issued date
 : February 20, 2015

 Revised date
 : March 10, 2015

 FCC ID
 : UCE314062A

Radiated emission




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10636726H-G-R3

Page : 27 of 28

Issued date : February 20, 2015 Revised date : March 10, 2015 FCC ID : UCE314062A

Worst Case Position

Below 30MHz Y-axis

Above 30MHz Horizontal:X-axis / Vertical:X-axis





Y-axis



Z-axis



UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10636726H-G-R3

Page : 28 of 28

Issued date : February 20, 2015 Revised date : March 10, 2015 FCC ID : UCE314062A

With/Without Tag



With Tag



Without Tag

End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124