Test report No. : 10636726H-F-R3
Page : 159 of 160
Issued date : February 20, 2015
Revised date : March 17, 2015
FCC ID : UCE314062A

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1



Photo 2

UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10636726H-F-R3
Page : 160 of 160
Issued date : February 20, 2015
Revised date : March 17, 2015
FCC ID : UCE314062A

Worst Case Position : Horizontal: Z-axis/ Vertical: Y-axis

X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124