Test report No. : 10636726H-A-R1

Page : 55 of 57

Issued date : February 20, 2015 Revised date : March 5, 2015 FCC ID : UCE314062A

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10636726H-A-R1

Page : 56 of 57

Issued date : February 20, 2015 Revised date : March 5, 2015 FCC ID : UCE314062A

Radiated Spurious Emission




Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10636726H-A-R1 Page : 57 of 57

Issued date : February 20, 2015
Revised date : March 5, 2015
FCC ID : UCE314062A

Worst Case Position

Below 1GHz (Horizontal: X-axis/ Vertical: X-axis) Above 1GHz (Horizontal: X-axis/ Vertical: Z-axis)







End of Report

UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124