





Inside View of The EUT



Report no. ETLE060609.252, Page 1 of 10


EMC Lab : #584 Sangwhal-ri, Ganam-myeon, Yoju-gun, Gyounggi-do, 469-885, Korea Tel:82-31-885-0072, Fax:82-31-885-0074 ETLQP-21-F22-0







Component side view of Main board




Report no. ETLE060609.252, Page 2 of 10





Solder side view of Main board



Report no. ETLE060609.252, Page 3 of 10










Inside View of The LNB TUNER






Report no. ETLE060609.252, Page 4 of 10







Component side view of Power board



Report no. ETLE060609.252, Page 5 of 10

Head Office: # 371-51 Gasan-dong, Geumcheon-gu, Seoul, 153-803, Korea Tel: 82-2-858-0786 Fax: 82-2-858-0788


EMC Lab: #584 Sangwhal-ri, Ganam-myeon, Yoju-gun, Gyounggi-do, 469-885, Korea Tel:82-31-885-0072, Fax:82-31-885-0074 ETLQP-21-F22-0







Solder side view of Power board




Report no. ETLE060609.252, Page 6 of 10








Component side view of Front Board



Solder side view of Front Board




Report no. ETLE060609.252, Page 7 of 10








Inside View of The EUT of RF Modulator





Report no. ETLE060609.252, Page 8 of 10







View of Bottom cover



View of Top cover



Report no. ETLE060609.252, Page 9 of 10







View of Front Cover

