

Report No. : FR480825

## **Appendix A. Test Photos**

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01





Report No. : FR480825

#### 1 Photographs of Conducted Emissions Test Configuration

Mode 1



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A2 of A6

Report Version

: Rev. 01





Report No. : FR480825



**SIDE VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01






# 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A4 of A6

Report Version

: Rev. 01

Report No. : FR480825



### FCC Radio Test Report


Report No. : FR480825

: A5 of A6


: Rev. 01

For radiated emissions 30MHz~1GHz

Mode 2



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version




#### FCC Radio Test Report


Report No. : FR480825

For radiated emissions above 1GHz

Mode 1



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A6 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01